

ESM Solutions - Sourcing - Line Item Bid

Event ID B18042R2  
 Event Name GEIL-12 DKB-12 KILN or Equivalent  
 Section Name Standard Line Item Pricing  
 Section Attachments

Summary	
GEIL	\$ 23,099.00
Dynamic	\$ 27,938.80

Supplier Name	Response Notes	Response Attachment	Item/Service (Required - Entity)	Quantity (Required - Entity)	Unit Bid Price (Required - Supplier)	Extended Bid Price	Notes	SupplierNotes	Attachments	NoBid
Dynamic Interactive Business System Inc	Does not include installation training or startup.	BID Document	Geil DLB-12 Kiln or equivalent: 12-16 c.f. front loading down draft; door hinge: right side  If bidding an equivalent product, please make note of the manufacturer and model number in the notes section of this line item.	1	\$ 22,030.80	\$ 22,030.80				No
Dynamic Interactive Business System Inc	Does not include installation training or startup.	BID Document	Vent hood	1	\$ 1,800.00	\$ 1,800.00				No
Dynamic Interactive Business System Inc	Does not include installation training or startup.	BID Document	Shelf and furniture kit for kiln	1	\$ 1,008.00	\$ 1,008.00				No
Dynamic Interactive Business System Inc	Does not include installation training or startup.	BID Document	Freight Charges	1	\$ 3,100.00	\$ 3,100.00				No
GEIL KILNS	BID PRICE DOES NOT INCLUDE ANY INSTALLATION, TRAINING OR START UP.		Geil DLB-12 Kiln or equivalent: 12-16 c.f. front loading down draft; door hinge: right side  If bidding an equivalent product, please make note of the manufacturer and model number in the notes section of this line item.	1	\$ 17,971.00	\$ 17,971.00		GEIL KILNS DLB-12		No
GEIL KILNS	BID PRICE DOES NOT INCLUDE ANY INSTALLATION, TRAINING OR START UP.		Vent hood	1	\$ 1,500.00	\$ 1,500.00		VENT HOOD ONLY		No
GEIL KILNS	BID PRICE DOES NOT INCLUDE ANY INSTALLATION, TRAINING OR START UP.		Shelf and furniture kit for kiln	1	\$ 840.00	\$ 840.00				No
GEIL KILNS	BID PRICE DOES NOT INCLUDE ANY INSTALLATION, TRAINING OR START UP.		Freight Charges	1	\$ 2,788.00	\$ 2,788.00		FREIGHT DOES NOT INCLUDE OFFLOADING. SCHOOL IS RESPONSIBLE FOR OFFLOADING FROM TRUCK		No